Central Region

No.	Name of Plant	MOE Office Location	Sector	Type of Concern	Status Report based on Information Received from Jan 1 - Dec 31, 1997
1	Tonolli Ltd	Halton/Peel	Misc.	Reg. 337	 Exceeded daily concentration limit for lead (2 ug/m3). Exceeded daily concentration limit for TSP (120 g/m3).
2	Hall Train Moving	Halton/Peel	Misc.	EPA	 Operating without required Certificate of Approval - Jan 1 - Apr 30.
3	Nabisco	Halton/Peel	Misc.	Reg. 360	Failed to notify for spill - Mar 18.
4	Flamingo Custom Woodwork	Toronto	Misc.	CA	Failed to comply with Certificate of Approval conditions - Apr 11.
5	Wabash Alloys	Toronto	Misc.	SR	 Released metallic dust in non-compliance with sectoral regulation - Mar 26.
6	Canada Metal	Toronto	Misc.	СО	Failed to monitor for lead from Mar 4 to Dec 31.
7	Canac Kitchens	York/Durham	Misc.	СО	Failed to submit study in compliance with control order - Jan 10.

April 20/99

Notes:

Central Region

No.	Name of Plant	MOE Office Location	Sector	Type of Concern	Status Report based on Information Received from Jan 1 - Dec 31, 1997
8	Thorton Cemetery	York/Durham	Misc.	CA	Failed to comply with Certificate of Approval conditions - Mar 13.
9	Helins Oils	York/Durham	Misc.	EPA	Released Dowtherm A (odour) causing an adverse affect from Apr 21 to Sep 11.
10	Ajax Energy/Energy Plus 2000	York/Durham	Misc.	Reg 346	Released smoke causing an opacity exceedance.

April 20/99

^{1.} Type of Concern indicates whether the non-compliance was with a Control Order (CO), Certificate of Approval (CA), Sectoral Regulation (SR), specific regulation or Act.

Eastern Region

No.	Name of Plant	MOE Office Location	Sector	Type of Concern	Status Report based on Information Received from Jan 1 - Dec 31, 1997
11	Lafarge Canada	Kingston	Industrial Minerals	Reg. 346	Released dust causing an opacity exceedance.
12	Dupont Canada Inc.	Kingston	Organic Chemical	CA	Failed to obtain Certificate of Approval amendment.
13	Hydro Agri Canada L.P/S.E.C.	Kingston	Inorganic Chemical	Reg 346 CA	 Released particulate exceeding 100 ug/m3. Released NO_x exceeding 2500 ug/m3
14	Longevity Acrylics Inc.	Kingston (Cornwall)	Misc.	Reg 346	 Exceeded limit for styrene (400 ug/m3). Failed to obtain Certificate of Approval amendment.

April 20/99

^{1.} Type of Concern indicates whether the non-compliance was with a Control Order (CO), Certificate of Approval (CA), Sectoral Regulation (SR), specific regulation or Act.

Northern Region

No.	Name of Plant	MOE Office Location	Sector	Type of Concern	Status Report based on Information Received from Jan 1 - Dec 31, 1997
15	Inco Limited - Smelter Ontario Division	Sudbury	Mining	CO SR	 Exceeded the stack limit of 0.5 ppm - 1 hour average for SO2 a total of 4 times. (Aug 3, Sep 26, Oct 15, Dec 7) Exceeded the mobile unit limit of 0.5 ppm - 1 hour average for SO2 a total of 2 times. (Aug 29, Oct 1) Released fugitive emissions exceeding the limit of 0.3 ppm - ½ hour average for SO2 a total of 5 times. (Oct 21, 29, Nov 14, Dec 10 twice)
16	Inco Limited - Copper Refinery	Sudbury	Mining	СО	Released trace metals causing an opacity exceedance.
17	Domtar Recovery	Thunder Bay	Misc.	Reg. 346	Released particulate causing an opacity exceedance - Mar 4.
18	Falconbridge Ltd. Kidd Creek Metallurgical Site	Timmins	Mining	SR	Released fugitive emissions exceeding the limit of 0.3 ppm - ½ hour average for SO2 a total of 21 times. (Jan 13,16,17 twice,18, Feb 5, Mar 20 twice,23 twice, Jun 26, Jul 5, Aug 1, Sep 4,5,17, Oct 23,24,29, Nov 17, Dec 13)

April 20/99

^{1.} Type of Concern indicates whether the non-compliance was with a Control Order (CO), Certificate of Approval (CA), Sectoral Regulation (SR), specific regulation or Act.

Northern Region

No.	Name of Plant	MOE Office Location	Sector	Type of Concern	Status Report based on Information Received from Jan 1 - Dec 31, 1997
19	Grant Forest Products	Timmins	Misc.	CA	 Released particulate exceeding Certificate of Approval limit.

April 20/99

^{1.} Type of Concern indicates whether the non-compliance was with a Control Order (CO), Certificate of Approval (CA), Sectoral Regulation (SR), specific regulation or Act.

Southwestern Region

No.	Name of Plant	MOE Office Location	Sector	Type of Concern	Status Report based on Information Received from Jan 1 - Dec 31, 1997
20	Elkay Canada Ltd.	Barrie	Misc.	EPA	 Operating without required Certificate of Approval - Oct 29.
21	Paramount Auto	Barrie	Misc.	EPA	• Operating without required Certificate of Approval - Oct 27.
22	Interforest Ltd.	Owen Sound	Misc.	EPA	 Operating without required Certificate of Approval - Jul 21.
23	Ethyl	Sarnia	Misc.	Reg. 189	Released freon (CFC) to atmosphere - Feb 14.
24	Suncor	Sarnia	Misc.	SR	Released SO2 exceeding limit (830 ug/m3) - Mar 21.
25	Pearson Equipment Rental	Sarnia	Misc.	EPA	 Operating without required Certificate of Approval - Mar 27.
26	Sarnia Quicklube	Sarnia	Misc.	EPA	 Operating without required Certificate of Approval - Mar 21.
27	Bridgeview Marina	Sarnia	Misc.	EPA	 Operating without required Certificate of Approval - Jan 23.

April 20/99

^{1.} Type of Concern indicates whether the non-compliance was with a Control Order (CO), Certificate of Approval (CA), Sectoral Regulation (SR), specific regulation or Act.

Southwestern Region

No.	Name of Plant	MOE Office Location	Sector	Type of Concern	Status Report based on Information Received from Jan 1 - Dec 31, 1997
28	Sarnia Smart Cars	Sarnia	Misc.	EPA	 Operating without required Certificate of Approval - Jul 15.
29	Final Touch Furniture Finishing	Sarnia	Misc.	EPA	 Operating without required Certificate of Approval - Jun 19.
30	Procor Ltd.	Sarnia	Misc.	CA	Failed to comply with Certificate of Approval condition - Jul 10.
31	AAROC Aggregates	London	Misc.	EPA	Operating without required Certificate of Approval - May 8.
32	RIPCO	London	Misc.	EPA	 Operating without required Certificate of Approval - May 22.
33	Hassan Steel Fabricators Ltd.	London	Misc.	CA	Failed to comply with Certificate of Approval condition re modifications to paint spray booth - Dec 9.
34	Trim Rite	London	Misc.	EPA	 Operating without required Certificate of Approval - Sep 26.

April 20/99

Notes:

Southwestern Region

No.	Name of Plant	MOE Office Location	Sector	Type of Concern	Status Report based on Information Received from Jan 1 - Dec 31, 1997
35	Richwood Kitchens	London	Misc.	EPA	 Operating without required Certificate of Approval - Dec 5.
36	Standard Tube	London	Misc.	EPA	 Operating without required Certificate of Approval - May 14.
37	Sachs Automotive	London	Misc.	EPA	 Operating without required Certificate of Approval - May 22.
38	Matrix Adhesive	London	Misc.	EPA	 Operating without required Certificate of Approval - Jun 5.
39	Hobart Brothers	London	Misc.	EPA	 Operating without required Certificate of Approval - Jun 23.
40	Archibald - Leyton	London	Misc.	EPA	 Operating without required Certificate of Approval - Jul 16.
41	Quality Sandblasting	London	Misc.	EPA	 Operating without required Certificate of Approval - Oct 10.

April 20/99

Notes:

West Central Region

No.	Name of Plant	MOE Office Location	Sector	Type of Concern	Status Report based on Information Received from Jan 1 - Dec 31, 1997
42	Stelco	Hamilton	Iron and Steel	Reg. 346	 Released particulate causing an opacity exceedance.
43	Dofasco	Hamilton	Iron and Steel	Reg. 346	 Released particulate causing an opacity exceedance.
44	Columbian Chemicals	Hamilton	Inorganic Chemicals	Reg. 346	 Released particulate causing an opacity exceedance.
45	Ontario Hydro TGS	Hamilton	Electric Power	Reg. 346	 Released particulate causing an opacity exceedance.
46	SWARU	Hamilton	Municipal	Reg. 346	Released particulate causing an opacity exceedance.
47	Empire Transportation Ltd.	Niagara	Misc.	EPA	 Operating without required Certificate of Approval - Dec 17 - Dec 31.
48	Erie Powder Coatings	Niagara	Misc.	EPA	 Operating without required Certificate of Approval - Nov 25 - Dec 31.

April 20/99

^{1.} Type of Concern indicates whether the non-compliance was with a Control Order (CO), Certificate of Approval (CA), Sectoral Regulation (SR), specific regulation or Act.

West Central Region

No.	Name of Plant	MOE Office Location	Sector	Type of Concern	Status Report based on Information Received from Jan 1 - Dec 31, 1997
49	Green Line Equipment	Niagara	Misc.	EPA	 Operating without required Certificate of Approval - Nov 28 - Dec 31.
50	Harvey Easson Transport Inc.	Niagara	Misc.	CA	Failed to comply with Certificate of Approval condition re waste oil burner - Dec 29.
51	Import Auto Collision	Niagara	Misc.	EPA	 Operating without required Certificate of Approval - Sep 25 - Dec 31.
52	ITT Automotive	Niagara	Misc.	EPA	Released particulate causing an adverse affect - Oct 11, 29.
53	J.S. Parker International Ltd.	Niagara	Misc.	EPA	Released paint fumes causing an adverse affect - Oct 11 - Dec 31.
54	Maple Leaf Garage & Auto Bodies Limited	Niagara	Misc.	CA	Failed to re-apply in accordance with Certificate of Approval condition - January 1 - Dec 31.
55	Penisula Ready Mix	Niagara	Misc.	EPA	Released dust causing an adverse affect - May 21.

April 20/99

^{1.} Type of Concern indicates whether the non-compliance was with a Control Order (CO), Certificate of Approval (CA), Sectoral Regulation (SR), specific regulation or Act.

West Central Region

No.	Name of Plant	MOE Office Location	Sector	Type of Concern	Status Report based on Information Received from Jan 1 - Dec 31, 1997
56	Peter Freedema	Niagara	Misc.	EPA	Released smoke from burning plastics causing an adverse affect - Jul 10.
57	Plazek Auto Recyclers	Niagara	Misc.	EPA	 Operating without required Certificate of Approval - May 21 - Dec 18.
58	Sicard Holiday Campers	Niagara	Misc.	EPA	Operating without required Certificate of Approval - Dec 1 - Dec 31.

April 20/99

Notes: